

ASTROMENS

Astrovan Sub-Frame Pictures

Rebuilding the sub-frame.

[Home](#)

[Donor Vehicle Pictures](#)

This page is the rebuilding of the sub-frame for a 1986 Astro with 90K miles on it. The sub-frame came from a donor vehicle but had to be totaly rebuilt including control arm bushings, ball joints, springs, shocks, and body mounts.



Sub-frame just out of donor vehicle



Body mount hole needing repair



Cutting out ball joints



Repairing body mount holes with new steel



**Control arms painted and ready
for reassembly**



Spindles painted and ready to be installed



**Sub-frame, sanded, cleaned, painted,
control arms mounted 1**



**Sub-frame, sanded, cleaned, painted,
control arms mounted 2**



Springs, shocks, spindles installed 1



Springs, \shocks, spindles installed 2



Close up of front suspension 1



Close up of front suspension 2



Complete with new brake lines the frame is all ready for install



Close up of front suspension

[Home](#)